

Exhibit 3: Project Photographs



Localized bank failure along the Arroyo de la Laguna.

Exhibit 3: Project Photographs



Typical denuded channel in urban area.